

701-MD REAR VIEW

IMPORTANT: INPUT MUST BE WIRED TO BATTERY SIDE

HEAVY DUTY LOADS

REMOTE KEY SWITCH

INPUT

OUTPUT

PLUG

SOCKET

RED 1
GREEN 2
BLACK 3

3 2 1

1 2 3

LED

+

ON/OFF SWITCH

THESE TWO CABLES MUST BE TERMINATED INTO DEUTSCH PLUG

BATTERY

IT IS IMPERATIVE THAT THE NEGATIVE (BLACK) FOR THIS UNIT IS TAKEN FROM THE SAME BATTERY THAT THE MD IS ISOLATING. FAILURE TO DO THIS WILL CAUSE THE UNIT TO WORK ERRATICALLY. ONLY ONE NEGATIVE MUST BE SUPPLIED TO EACH UNIT FOR CORRECT OPERATION.

