


Raritan 53101* Macerator Pump with Waste Valve



The Problem

Whether it's your impeller or other issues that causes you to service your macerator pump, it could be a messy job for either you or your technician. At Raritan, our engineers have developed a better, cleaner way to service your macerator pump.

The Solution – Raritan's 53101* Macerator Pump with Gate Valve

The 53101 macerator pump has a unique waste valve that isolates the impeller housing from the holding tank discharge port. When engaged, the waste valve greatly reduces the amount of spillage caused when servicing the discharge pump. With limited installation space below decks, the 53101 pump is an ideal choice. The 53101 pump eliminates the option of an external ball valve, which requires more space and adds more connection points to your sanitation system.

Pump Features:

- Special nitrile-rubber impeller, tested to run dry 3x longer the competition
- Spring-loaded viton motor shaft seal
- Special seals and epoxy-coated motor
- Stainless steel fasteners
- Heavy duty steel chopper
- Available in 12 and 24 volts DC

Optional Smart Macerator Control (SMC)

- Additional dry run protection
- Auto shut down
- Periodically moves the impeller to avoid binding

* Please specify either 12 or 24 volt when ordering

How the waste valve works

